U.S. Serial No. 10/658,496 Atty. Docket: JD-276-US

Examiner: Not yet assigned

Art Unit: 3752 Page 4 of 4

REMARKS

These amendments are being made to correct errors in the specification and drawings.

The revision in the specification at paragraph 00058 is made to properly refer to passages 90-94 in FIGURES 9-11.

The revision in FIGURE 4 is to conform the eductor 24 to that shown in FIGURES 3, 5 and 6. It should be noted that the number 50 is not employed.

The revisions in FIGURE 6 are to make proper reference to seals 64 and 66.

Reference to the correct number "132" can be found on page 10 of the specification.

Substitute formal drawings incorporating the corrections are submitted herewith.

With entry of the amendment early action on the merits is respectfully requested.

Respectfully submitted,

Dated: 13 October 2004

JohnsonDiversey, Inc. 8310 16th Street, M/S 509 P.O. Box 902

Sturtevant, Wisconsin 53177-0902 Direct Phone: (262) 631-4583

Facsimile: (262) 631-4021

Neil E. Hamilton

Attorney for Applicants

Reg. No. 19,869

U.S. Serial No. 10/658,496 Atty. Docket: JD-276-US

Examiner: Not yet assigned Art Unit: 3752

Art Unit: 3752 Page 3 of 4

IN THE DRAWINGS:

In FIGURE 4, please delete the number "50" and revise eductor 24 as indicated.

In FIGURE 6, please delete number 64 and the lead line.

In FIGURE 6, please change number 66 to 64.

In FIGURE 11, please correct reference number "128" to --132--.

In FIGURE 16, please delete the heading.

These corrections are indicated in red ink on the attached drawing sheets.